Report Date: October 25, 2000 Calendar Quarter: 1

Safety Recall Quarterly Report from: August 28, 2000 through September 30, 2000

Manufacturer: Fleetwood Enterprises, Inc.

Report Author: Robert E. Wozniak Phone: 909-351-3814

Recall Subject: 97-00 Bounder Diesel/Discovery Power Steering Hydraulic Hose Routing

NHTSA Safety Recall Campaign Number: 00V-204

Also, for completeness, if your company has assigned a code number to this campaign, provide your code: 00724

(a) The date notification to purchasers began:

1st mailing: August 28, 2000

2<sup>nd</sup> meiling:

- (b) The date the 3<sup>rd</sup> notification mailing to purchasers was completed:
- The total number of items involved: 4711

The total number of items involved in the subject campaign (including all items sold or distributed to purchasers, dealers, distributors, and similar entities beyond the immediate control of the manufacturer / importer).

Number of items returned from inventory or remedied prior to sale: 0
Includes (a) the total number of items returned from manufacturer, distributor, dealer or retailer inventory or (b) otherwise remedied prior to sale to consumers. Do not include this number in 4 (a) or 4 (b).

- 4. (a) Total number inspected and remedied: 655

  Total number of items which were inspected and/or otherwise repaired or remedied (cumulative).
  - (b) Total number inspected and NOT REQUIRING REMEDY: 51 Total number of items involved in the recall and inspected, but determined to NOT REQUIRE REMEDIAL or recall repair work.
- Items determined to be UNREACHABLE;

Report Date: January 17, 2001 Calendar Quarter: 2

Safety Recall Quarterly Report from: August 28, 2000 through December 31, 2000

Manufacturer: Fleetwood Enterprises, Inc.

Report Author: Robert E. Wozniak Phone: 909-351-3814

Recall Subject: 97-00 Bounder Diesel/Discovery Power Steering Hydraulic Hose Routing

NHTSA Safety Recall Campaign Number: 00V-204

Also, for completeness, if your company has assigned a code number to this campaign, provide your code: 00724

(a) The date notification to purchasers began:

1st mailing: August 28, 2000

2<sup>nd</sup> mailing:

- (b) The date the 3rd notification mailing to purchasers was completed:
- The total number of items involved: 4711

The total number of items involved in the subject campaign (including all items sold or distributed to purchasers, dealers, distributors, and similar entities beyond the immediate control of the manufacturer / importer).

Number of items returned from inventory or remedied prior to sale: 0
Includes (a) the total number of items returned from manufacturer, distributor, dealer or retailer inventory or (b) otherwise remedied prior to sale to consumers. Do not include this number in 4 (a) or 4 (b).

- (a) Total number inspected and remedied: 1351
   Total number of items which were inspected and/or otherwise repaired or remedied (cumulative).
  - (b) Total number inspected and NOT REQUIRING REMEDY: 108

    Total number of items involved in the recall and inspected, but determined to NOT REQUIRE REMEDIAL or recall repair work.
- Items determined to be UNREACHABLE:

Report Date: April 27, 2001 Calendar Quarter: 4

Safety Recall Quarterly Report from: April 20, 2000 through March 30, 2001

Manufacturer: Fleetwood Enterprises, Inc.

Report Author: Robert E. Wozniak Phone: 909-351-3814

Recall Subject: 96-99 Jamboree & Tioga Spare Wheel

NHTSA Safety Recall Campaign Number: 00V-104

Also, for completeness, if your company has assigned a code number to this campaign, provide your code: 00229

(a) The date notification to purchasers began:

1<sup>st</sup> mailing: May 3, 2000 2<sup>st</sup> mailing: July 12, 2000

- (b) The date the 3<sup>rd</sup> notification mailing to purchasers was completed:
- The total number of items involved: 3897

The total number of items involved in the subject campaign (including all items sold or distributed to purchasers, dealers, distributors, and similar entitles beyond the immediate control of the manufacturer / importer).

Number of items returned from inventory or remedied prior to sale: 0
Includes (a) the total number of items returned from manufacturer, distributor, dealer or retailer inventory or (b) otherwise remedied prior to sale to consumers. Do not include this number in 4 (a) or 4 (b).

- 4. (a) Total number inspected and remedied: 1185

  Total number of items which were inspected and/or otherwise repaired or remedied (cumulative).
  - (b) Total number inspected and NOT REQUIRING REMEDY: 207

    Total number of items involved in the recall and inspected, but determined to NOT REQUIRE REMEDIAL or recall repair work.
- Items determined to be UNREACHABLE:

Total number exported: Total number stolen: Total number scrapped: Total number unable to identify:	2 0 0	
		0
		Total number otherwise unreachable:

Report Date: July 6, 2001 Calendar Quarter: 4

Safety Recall Quarterly Report from: August 28, 2000 through June 30, 2001

Manufacturer: Fleetwood Enterprises, Inc.

Report Author: Robert E. Wozniak Phone: 909-351-3814

Recall Subject: 97-00 Bounder Diesel/Discovery Power Steering Hydraulic Hose Routing

1. NHTSA Safety Recall Campaign Number: 00V-204

Also, for completeness, if your company has assigned a code number to this campaign, provide your code: 00724

2. (a) The date notification to purchasers began:

1<sup>st</sup> mailing: August 28, 2000 2<sup>nd</sup> mailing: February 5, 2001

- (b) The date the 3<sup>rd</sup> notification mailing to purchasers was completed:
- The total number of items involved: 4711

The total number of items involved in the subject campaign (including all items sold or distributed to purchasers, dealers, distributors, and similar entities beyond the immediate control of the manufacturer / importer).

Number of items returned from inventory or remedied prior to sale: 0
Includes (a) the total number of items returned from manufacturer, distributor, dealer or retailer inventory or (b) otherwise remedied prior to sale to consumers. Do not include this number in 4 (a) or 4 (b).

- 4. (a) Total number inspected and remedied: 2796

  Total number of items which were inspected and/or otherwise repaired or remedied (cumulative).
  - (b) Total number inspected and NOT REQUIRING REMEDY: 228
    Total number of items involved in the recall and inspected, but determined to NOT REQUIRE REMEDIAL or recall repair work.
- 5. Items determined to be UNREACHABLE:

Report Date: October 22, 2001 Calendar Quarter: 5

Safety Recall Quarterly Report from: August 28, 2000 through October 1, 2001

Manufacturer: Fleetwood Enterprises, Inc.

Report Author: Robert E. Wozniak Phone: 909-351-3814

Recall Subject: 97-00 Bounder Diesel/Discovery Power Steering Hydrau lie Hose Routing

NHTSA Safety Recall Campaign Number: 00V-204

Also, for completeness, if your company has assigned a code number to this campaign, provide your code: 00724

(a) The date notification to purchasers began:

Is mailing: August 28, 2000 2nd mailing: February 5, 2001

- (b) The date the 3<sup>rd</sup> notification mailing to purchasers was completed:
- The total number of items involved: 4711

The total number of items involved in the subject campaign (including all items sold or distributed to purchasers, dealers, distributors, and similar entities beyond the immediate control of the manufacturer / importer).

Number of items returned from inventory or remedied prior to tale: 0 Includes (a) the total number of items returned from manufacturer, distributor, dealer or retailer inventory or (b) otherwise remedied prior to sale to consumers. Do not include this number in 4 (a) or 4 (b)

- (a) Total number inspected and remedied: 2958
   Total number of items which were inspected and/or otherwise repaired or remedied (cumulative).
  - (b) Total number inspected and NOT REQUIRING REMEDY: 239 Total number of items involved in the recall and inspected, but determined to NOT REQUIRE REMEDIAL or recall repair work.
- Items determined to be UNREACHABLE:

Report Date: January 8, 2002 Calendar Quarter: 6

Safety Recall Quarterly Report from: August 28, 2000 through January 1, 2002

Manufacturer: Flootwood Enterprises, Inc.

Report Author: Robert E. Wozniak Phone: 909-351-3814

Recall Subject: 97-00 Bounder Dissel/Dissovery Power Steering Hydraulic Hose Routing

NHTSA Safety Recall Campaign Number: 90V-204

Also, for completeness, if your company has assigned a code number to this campaign, provide your code: 90724

(a) The date notification to purchasers began:

1" mailing: August 28, 2000 | 2" mailing: February 5, 2001

- (b) The date the 3<sup>rd</sup> notification mailing to purchasers was completed:
- The total number of items involved: 4711

The total number of items involved in the subject campaign (including all items sold or distributed to purchasers, dealers, distributors, and similar entities beyond the immediate control of the manufacturer / importer).

Number of items returned from inventory or remedied prior to sale: 0 becludes (a) the total number of items returned from manufacturer, distributor, dealer or retailer inventory or (b) otherwise remedied prior to sale to consumers. Do not include this number in 4 (a) or 4 (b).

- (a) Total number inspected and remedied: 3078
   Total number of items which were inspected and/or otherwise repaired or remedied (cuandative).
  - (b) Total number inspected and NOT REQUIRING REMEDY: 263 Total number of items involved in the recall and inspected, but determined to NOT REQUIRE REMEDIAL or recall repair work.
- Items determined to be UNREACHABLE: